



This three week look ahead schedule is an APPROXIMATION of how the work will progress. Minor changes to the 3WK LA are to be expected as the work progresses.

3/30/2011

Area / Activity Description	Resp.	Shift	Escort Req'd?	Week 1							Week 2							Week 3							Remarks	
				3/27	3/28	3/29	3/30	3/31	4/1	4/2	4/3	4/4	4/5	4/6	4/7	4/8	4/9	4/10	4/11	4/12	4/13	4/14	4/15	4/16		
				Su	M	T	W	Th	F	Sa	Su	M	T	W	Th	F	Sa	Su	M	T	W	Th	F	Sa		
<i>Chiller Room</i>																										
Pipe Hanger & Header Installation	JFW	1st	No																							
Set/Install New Pumps incl. Trim Piping, etc.	JFW	1st	No																							
Start Electrical Demolition / Layout / Rough-In in Mech. Rm	LECO	2nd	No																							
Begin ATC Rough-In	HW	1st	No																							
<b>Install New Chillers</b>	JFW	1st	No																							Loading dock must be free each day.
Install Trim Piping for New Chillers	JFW	1st	No																							
<i>CT-1 Structure/Exterior Work</i>																										
Drilling of Mini-Piles	MT	1st	No																							Delayed due to unforeseen soil conditions
Form Mini-Pile Caps	CC	1st	No																							
Pour Mini-Pile Caps / Curing Time	CC	1st	No																							
<i>CT-2&amp;3 Structure &amp; Cooling Tower Work</i>																										
Set New Cooling Towers # 2 & 3	VF	1st	No																							
Install CT Trim Piping, etc.	JFW	1st	No																							

**Schedule Legend:**

-  = Escort Required / Lab Personnel Notification Recommended
-  = Non-Sensitive Areas / No Escort Required